Product Bulletin

TRIMBLE TSC5 Android 13 Update

Some TSC5 units that upgraded from Android 11 to Android 13 (OS v03.00.04) experienced application crashes if the built-in GNSS subsystem did not have a good position fix. This issue was caused by an incompatibility between the GNSS driver and the Android 13 Location Manager. OS v03.00.04 also included a version of the carrier configuration database that did not permit modification of APN data for some carriers.

An updated OS with GNSS driver and carrier configuration fixes will be available the week of 19 February 2024. This update will be deployed OTA (over-the-air) initially to only those TSC5s that have already upgraded to Android 13. The user will be given a daily prompt for 7 days to install the update. To install, accept and download the update when prompted. Please refer to mcs.trimble.com for further details regarding this release.

This update provides a permanent fix to those TSC5s that already have Android13 and to those that will upgrade to Android 13 in the future.

For more information

For more information, contact your local Trimble sales representative.

https://mgispartners.trimble.com   **https://surveypartners.trimble.com**